



- S1 Limit switch CLOSED
- S2 Limit switch OPEN
- S7 Thermal switch integrated
- F1 Fuse
- H1 Lamp CLOSED
- H2 Lamp OPEN
- C Phase-shift capacitor
- U Open - Closed control switch

## EBRO ARMATUREN

Suggested wiring diagram for single-phase actuators  
without electronic torque control

**Attention:**  
The switches are shown inactive!  
The valve is in intermediate position!