



- S1 Limit switch CLOSED
- S2 Limit switch OPEN
- S7 Thermal switch integrated
- U Open - Closed control switch
- K1 Contactor CLOSED
- K2 Contactor OPEN
- F1 Motor fuses
- F2 Control fuse
- F3 Heater fuse
- H1 Lamp CLOSED
- H2 Lamp OPEN

EBRO ARMATUREN

Suggested wiring diagram for three-phase actuators without electronic torque control

Attention:
The switches are shown inactive!
The valve is in intermediate position!